cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11157	Main Street: N_IRWIN_AV			Cross	Street:	W_6TH_ST	Location:	W				
ADA ID: 69465F7C2B85	Ramp Type: Directional1			Initial	Initial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	5			
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description				
a state to		Remove & Replace Entire	e Ran	מו.	N/A	Ramp Length (in)	47.0	Yes	Grade Break?	Yes		
	X	Remove & Replace Gutte			Yes	Ramp Width (in)	71.0	Yes	Grade Break Slope (%)	5.0		
		-			Yes	Ramp Slope (%)	7.9	Yes	Grade Break XSlope (%)	2.0		
	Xe				Yes	Ramp XSlope (%)	0.9					
COM CON	1 1/2				No	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
					N/A	Flare Slope LT (%)	N/A	Yes	Flare Slope RT (%)	4.1		
	1. 100	Surveyor Notes:			N/A	Flare Traversable L	.T? No	N/A	Flare Traversable RT?	Yes		
E. C.		N/A			Yes	Landing Length (in)) 71.0	Yes	DWS Provided?	Yes		
					Yes	Landing Width (in)	71.0	Yes	DWS Contrast?	Yes		
	A ALA				No	Landing Slope (%)	2.4	Yes	DWS Length (in)	24.5		
					Yes	Landing X Slope (%	6) 0.2	Yes	DWS Full Width?	Yes		
	7 M	PROW/ADA:			N/A	Landing Curb? (Y/N	N) N/A	Yes	DWS Offset LT (in)	0.0		
	V States	Not Found, R304.2.2-Per	5. R30	04.3.2-	N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	26.0		
	A CA	Para, R304.2.3, R304.5.3	-, -		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.8		
	AVA.				Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.7		
	Law: No				N/A	Painted X Walk1?	No		Road Slope (%)	1.0		
Street 1 Name	W 6TH ST					X Walk 1 Direction	To NE		Road X Slope (%)	1.1		
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	Yes		
Street 2 Name	N/A					X Walk 1 Slope (%)) 1.0	N/A	Clear Space to XWalk (in)	N/A		
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%) 1.1	Yes	Storm Grate/Utility Hazard?	No		
					N/A	Ramp inside XWalk	<1? N/A		Storm Grate/Utility Type			
					Yes	Any Obstructions?	No			N/A		
		Total Cost:	\$	2350.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good		
							N/A	No	Curb Slope (%)	8.6		

