cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9061 M	Main Street: LUCENA_ST			RRIS_AV	Location:	N		
ADA ID: 695DD4962787 R	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance			ce: No	Severity Score:	46.25
Codes/Mitigation Info/Possible Solution Field Measurements/Component Comp								
	Possible Solutions:	<u>c</u>	Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp	With N	l/ A Rai	mp Length (in)	41.0	No	Ramp Slope (%)	10.7
	Two New Directional Ramps or		l o Rai	mp Width (in)	45.0	No	Ramp XSlope (%)	7.6
REAL REAL FROM	Equivalent.	Ν	/ A Fla	are Type LT	N/A	N/A	Flare Type RT	N/A
		N	l/ A Fla	are Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A A A A A A A A A A A A A A A A A A A		N	l/ A Fla	are Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N	l/ A Lar	nding Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N	l/ A Lar	nding Width (in)	N/A	N/A	DWS Contrast?	N/A
A The Alexander of the second	N/A	N	l/ A Lar	nding Slope (%)	N/A	N/A	DWS Length (in)	N/A
6		N	l/ A Lar	nding X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6	a set	N	l/ A Lar	nding Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A151	N	l/ A Sha	ared Landing?	N/A			
a b	PROW/ADA:	N	l/ A Gu	Itter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2	. N	/ A Gu	itter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A	R304.5.3		l/ A Pai	inted X Walk1?	Yes	N/A	Painted X Walk2?	No
			ΧV	Walk 1 Direction	To SW		X Walk 2 Direction	To SE
		N	XX XV	Valk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name NORI	RIS AV		ΧV	Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	0.9
Stop Condition-Street 2	None		ΧV	Nalk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	6.8
Street 2 Name LUCE	ENA ST	N	l/ A Rai	mp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 Sto	opSign		Roa	ad Slope (%)	4.0	N/A	Clear Space?	N/A
•				ad X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
		Ν		y Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		ostruction Type			Storm Grate/Utility Type	
				21	N/A		5 51	N/A
						Yes	Surface Condition? (G/P)	Good

<image>