## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interrection ID: 40044000	Main Ot			Oreas	Otro etc				Lesstien	
Intersection ID: 10041968	Main Street: WINDSOR_CASTLE_LN				Street:	N/A	Location:	N		
ADA ID: 69F21DE35F29	D: 69F21DE35F29 Ramp Type: Directional1				Pass/Fa	ail: Fail Overall	o Severity Score:	33.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
ALL AND		Possible Solutions:			Compliance Description			Data Compliance Description		
1100		Remove & Replace Er	ntire Ram	э.	N/A	Ramp Length (in)	131.0	N/A	Grade Break?	N/A
			-		No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0
No the second se	Ro				No	Ramp Slope (%)	10.7	N/A	Grade Break XSlope (%)	0.0
					No	Ramp XSlope (%)	5.1			
	C M				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
5 B	22 45	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second se		N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
B S A	Arel V				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	and the				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
Non Star	A Las	A			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
E E	- Phil	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	Lug	R304.5.1, R304.2.2, R	304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	RAN	,	•••		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
A A A A A A A A A A A A A A A A A A A				N/A	Painted X Walk1?	No		Road Slope (%)	0.9	
Street 1 Name E	ENTRANCE					X Walk 1 Direction	To SW		Road X Slope (%)	0.3
Stop Condition-Street 1	None					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	0.3	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	ļ
					N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	N/A	Curb Slope (%)	7.3





