

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5468 Main S	Main Street: N_TRYON_ST		eet:	J_W_CLAY_BV	Location:	E		
ADA ID: 6A19509A4924 Ramp	Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:	<u>C</u>	Compliance Description Date			a Compliance Description		Data
	Remove & Replace Entire Ramp	. N/	/ A	Ramp Length (in)	106.0	Yes	Ramp Slope (%)	7.6
A REP DE TRANSFER		N	0	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	1.0
		N/	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	7	N	/ A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N	/ A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N	/ A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N	/ A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
She she	14	N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N	/ A	Shared Landing?	N/A			
1 Julion State . State	PROW/ADA:	N	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
E E	R304.5.1	N/	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N	/ A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
131, Old Carlos and Carlos		N	/ A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name N TRYON ST	—			X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Signal				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N	/ A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N	/ A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

