

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28526	Main Sti	Main Street: ROLLINGBROOK_DR			Cross Street: TYVOLA_CENTRE_DR				NE
ADA ID: 6A732C787291	Ramp T	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A STATE A	Possible Solutions:		Compliance Description			Data Compliance Description		
	al with	Remove & Replace Entire Ra	amn	N/A	Ramp Length (in)	55.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	58.0	N/A	Grade Break Slope (%)	0.0
	Company & Bar W			Yes	Ramp Slope (%)	5.8	N/A	Grade Break XSlope (%)	0.0
	MUT THE ALL THE			No	Ramp XSlope (%)	3.8		1 ( )	
	SHART AND A			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	The Part of the Pa			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	0.0
	the for the	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	DE DE	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
PROW/ADA:				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0		DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A		DWS Offset LT (in)	N/A
G	1-2-	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
A I OF A A A A A A A A A A A A A A A A A A	a la desta desta Reservada desta	1,304.3.3		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	A MALL STREET			N/A	Painted X Walk1?	No		Road Slope (%)	6.9
Street 1 Name	ROLLINGBROOK DR	-			X Walk 1 Direction	To SW		Road X Slope (%)	3.6
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	6.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.6	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A		eterm erate/etancy type	N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
		· · · · · · · · · · · · · · · · · · ·				N/A	N/A	Curb Slope (%)	8.9
									0.0

