cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49894	tersection ID: 49894 Main Street: ROCKY_FORD_CLUB_RD Cr				RUTH_FERRELL_CT	Location:	Ν			
ADA ID: 6B8C29266D0	03 Ramp Type: BlendTrans1 li			itial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description			
22		Remove & Replace Curb Ra	mp With	N/A	Ramp Length (in)	73.5	Yes	BlendTrans Slope (%)	2.8	
		Two New Directional Ramps		No	Ramp Width (in)	45.0	Yes	BlendTrans XSlope (%)	0.3	
a france		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
1 Cox				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Aller				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A LAN TO		2		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
LE COL		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		LNDG GAP 2.0		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	A Carlos A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
1 72 L	1 LADON			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
a ame	4			N/A	Shared Landing?	N/A				
	And H	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
M 1 4/1	11 mil Maria	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Hot i cana, Rootion				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
and the second sec					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
	14 1 17 The				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	RUTH FERREL CT	_			X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	1.6	
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	1.8	
Street 2 Name	ROCKY FORD CLUB RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	None				Road Slope (%)	0.5		Clear Space?	N/A	
					Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

 Yes
 Surface Condition? (G/P)

 No
 Curb Slope (%)

Good

11.9



