cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10027081	ction ID: 10027081 Main Street: GALLERIA_BV			Cross Street: N/A				SE
ADA ID: 6CBF2D75E142	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No			Location: Severity Score:		
· · · · •			· · · ·					01.20
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description		Data
	Remove & Replace Curb		N/A	Ramp Length (in)	97.0	No	Ramp Slope (%)	8.8
	Two New Directional Ran	nps or	No	Ramp Width (in)	34.0	No	Ramp XSlope (%)	2.1
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
5.2	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
States to the states of the st	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	(All and a second se		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	, m x Z		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R3	04.2.2.	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	R304.5.3	- ,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
and a free the	.1141			X Walk 1 Direction	To N		X Walk 2 Direction	To NW
Contraction of the second	14711		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE			X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	2.6
Stop Condition-Street 2	StopSign			X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	0.1
Street 2 Name G	ALLERIA BV		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			Road Slope (%)	2.5	N/A	Clear Space?	N/A
				Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost:	\$ 3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A		2 21	N/A

Yes Surface Condition? (G/P)

Good





