

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14076	Main Street: W_TYVOLA_RD			Street:	WEST_BV	Location:	SW		
ADA ID: 6D2CB91916FC	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1 - Cape Maria	Possible Solutions:		Compliance Description			Data Compliance Description		
and the second sec	and and a second	Remove & Replace Entire Ram) .	N/A	Ramp Length (in)	95.0	N/A	Grade Break?	N/A
The state of the second state of	1			Yes	Ramp Width (in)	51.0	N/A	Grade Break Slope (%)	0.0
	1.			Yes	Ramp Slope (%)	3.0	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	6.7			
E & WEST EV				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A WEST BY	- 1			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	6 Carl	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A	LOCATED ON MEDIAN		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
6. G.				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
and the second sec	NO EN			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
Trio				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	1	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
A CONTRACTOR OF A				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	H. C. X			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
1) the state of the	100			N/A	Painted X Walk1?	No		Road Slope (%)	0.5
Street 1 Name	V TYVOLA RD				X Walk 1 Direction	To NE		Road X Slope (%)	6.8
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	6.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	5.8

