

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: N/A Main Street: SPEER\_BV Cross Street: MILLENNIUM\_AV Location: SW ADA ID: 6D811054C373 Ramp Type: Directional1 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



**SPEER BV** Street 1 Name Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A

1	Possible Solutions:				
1	Remove & Replace Entire Ramp.				
A.O.					
1					
19					
	Surveyor Notes:				
200	N/A				
No.					
S. S. Cont.					
1	PROW/ADA:				
	R304.2.2				
-					
Š					

PROW/ADA:			N
R304.2.2			1
			1
			1
			N
			1
			1
Total Cost:	\$	1600.00	

Field Measurements/Component Compliance									
Compl	iance Description	Data	Compli	ance Description	Data				
N/A	Ramp Length (in)	72.0	N/A	Grade Break?	N/A				
Yes	Ramp Width (in)	70.0	N/A	Grade Break Slope (%)	0.0				
No	Ramp Slope (%)	9.0	N/A	Grade Break XSlope (%)	0.0				
Yes	Ramp XSlope (%)	1.0							
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A				
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A				
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A				
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	No		Road Slope (%)	2.6				
	X Walk 1 Direction	То Е		Road X Slope (%)	2.8				
	X Walk 1 Width (in)	N/A		Clear Space?	N/A				
	X Walk 1 Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A				
	X Walk 1 X Slope (%)	2.8	N/A	Storm Grate/Utility Hazard?	N/A				
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type					
N/A	Any Obstructions?	N/A			N/A				
	Obstruction Type		Yes	Surface Condition? (G/P)	Good				
		N/A	N/A	Curb Slope (%)	4.7				





