cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•	-	-					
Intersection ID: 11331	Main Street: E_W_T_HARRIS_BV			Street:	MEADOW_ROSE_LN	Location:	SE		
ADA ID: 6E70E7573C14	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall	Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	AND CONTRACTOR	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	25.5	No	Ramp Slope (%)	8.4
Contraction of the second seco		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	4.5
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the state				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
THEON BD	AR	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
MILICIA		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E E	And the second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E. E.				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
Section 25 2	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
90	133			N/A	X Walk 1 Width (in)	89.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	MEADOW ROSE LN				X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	5.1
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	8.1		X Walk 2 X Slope (%)	1.9
Street 2 Name	E W T HARRIS BV			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	Signal				Road Slope (%)	4.6	N/A	Clear Space?	N/A
	U I				Road X Slope (%)	8.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
		• •				N/A			N/A
1									

Yes Surface Condition? (G/P)

Good

