cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·									
Intersection ID: 49248	248 Main Street: BOOMERANG_WY			Cross Street: PROSPERITY_VIEW_DR				Location:	NE
ADA ID: 6F2848D8C374	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	2 Ale	Possible Solutions:		Compliance Description Data			Comp	Compliance Description	
		Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	np With	N/A	Ramp Length (in)	46.0	Yes	BlendTrans Slope (%)	4.5
10			or	No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	2.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A Carton II				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6. A		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
BOOM TO BE		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
PROW/ADA:				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To S
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	BOOMERANG WY	-			X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	2.2
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	1.5
Street 2 Name	PROSPERITY VIEW DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	5.1		Clear Space?	N/A
					Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					<i>,</i> ,	N/A		, , ,	N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

15.0