cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Internection ID: 47976 Mein Street: MADVANNA CT | | | | | | | | | Location: | Е | |
|-----------------------------------------------------------------------------------------------------------------|----------------------------------|-------------------------|---------|------------------------------------------------|-----------------------------------------|-----------------------|--------------|-------------------|-----------------------------|-------|--|
| Intersection ID: 47876 | : 47876 Main Street: MARYANNA_CT | | CIUSS | Cross Street: WOODSORREL_LN | | | | | <u> </u> | | |
| ADA ID: 70AEFEEAA3DB Ramp Type: PerpDiag | | | Initial | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 10 | | |
| Codes/Mitigation Info/Possible Solution | | | | | Field Measurements/Component Compliance | | | | | | |
| | AL MASS | Possible Solutions: | | | Compliance Description | | Data Complia | | ance Description | Data | |
| | 1. 1. | Remove & Replace Curb | Ram | o With | N/A | Ramp Length (in) | 49.0 | Yes | Ramp Slope (%) | 5.1 | |
| | | Two New Directional R | • | | No | Ramp Width (in) | 47.2 | No | Ramp XSlope (%) | 3.1 | |
| | | Equivalent. | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | Co Y | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| di la | 42 | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| 6 Susalitation | | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | | Surveyor Notes: | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| the second se | \mathbf{A} | N/A | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | 4 90 | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| C. Martin | All and the | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| A CARLER CONTRACTOR | | | | | N/A | Shared Landing? | N/A | | | | |
| 5 | | PROW/ADA: | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | | Not Found, R304.5.1, R3 | 04.5.3 | 3 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | 1 | ,,, | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| A A A A A A A A A A A A A A A A A A A | | | | | | X Walk 1 Direction | To SW | | X Walk 2 Direction | To NW | |
| | | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name WOODS | ORREL LN | - | | | | X Walk 1 Slope (%) | 2.3 | | X Walk 2 Slope (%) | 5.2 | |
| Stop Condition-Street 2 | None | | | | | X Walk 1 X Slope (%) | 5.9 | | X Walk 2 X Slope (%) | 1.7 | |
| Street 2 Name MAR | RYANNA CT | | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | StopSign | | | | | Road Slope (%) | 3.8 | N/A | Clear Space? | N/A | |
| | | | | | | Road X Slope (%) | 5.9 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: | \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | | | N/A | | | N/A | |

Yes Surface Condition? (G/P)

Good

