

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

40.0

60.0

9.0

1.5

6.0

6.2

N/A

No

To E

N/A

5.2

4.1

N/A

Intersection ID: 28401 Main Street: WADE ARDREY RD **Cross Street: MARVIN RD** Location: NW **Overall Compliance: No Severity Score:** ADA ID: 71217F6370BF Ramp Type: Combination1Diag Initial Pass/Fail: Fail 0

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance Data

46.0

60.0

7.4

4.4

70.0

37.0

N/A

No

To S

N/A

2.5

3.9

N/A

N/A

Yes

No

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign WADE ARDREY RD None MARVIN RD Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3, R304.3.2

Total Cost:

Yes Ramp Slope LT (%) Ramp XSlope LT (%) No N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%)

N/A

N/A

Yes

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

X Walk 1 X Slope (%)

Ramp inside XWalk1?



3200.00

Road Slope (%) 3.6 Clear Space? N/A Road X Slope (%) 1.7 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 5.9 Curb Slope (%)



