## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42780	Main Str	reet: SILVERSWORD_DR	Cross S	ross Street: PURPLE_DAWN_DR				Location:	SW
ADA ID: 736E588F1660	Ramp Ty	Ramp Type: BlendTrans1			ail: Fail Overall C	o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	46.0	Yes	BlendTrans Slope (%)	3.7
		Two New Directional Ramps or		No	Ramp Width (in)	40.5	Yes	BlendTrans XSlope (%)	0.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
and the				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
TORDER		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		CURB GAP 1.5		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ALLIEREL				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
actives for the				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	11 mate				X Walk 1 Direction	To E		X Walk 2 Direction	To N
matter and					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	PURPLE DAWN DR	_			X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	4.0
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	6.1
Street 2 Name	SILVERSWORD DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	2.3		Clear Space?	N/A
					Road X Slope (%)	6.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
					<i>,</i> ,	N/A			N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

25.3