

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

XPOLog

Surface Condition? (G/P)

Good

Intersection ID: 5124	Main Street: GIBBON_RD			Cross Street: OLD_STATESVILLE_RD					Location:	NW	
ADA ID: 738B9A65506F	Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No						
Codes/Mitigation Info/Possible Solution				minut	Field Measurements/Component Compliance						
Possible Solutions:				Compliance Description Data Compliance Description Data							
1 C C C C C C C C C C C C C C C C C C C	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		ire Domi		N/A	Ramp Length (in)	59.0		Ramp Slope (%)	11.7	
and the second		Remove & Replace Ent	пе катр		No	Ramp Width (in)	42.5		Ramp XSlope (%)	1.9	
the second of the					N/A	Flare Type LT	42.5 N/A		Flare Type RT	N/A	
28 28 77 8					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A	
t.	B. B.				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
· · ·	Star 1	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
1 more el contente	5	-			N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A	
	GEBOM	N/A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	S				N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A N/A	
	The A					• • • •	N/A	N/A	DWS Oliset (III)	N/A	
	the states of th				N/A	Shared Landing?			$O_{\rm eff}$	NI/A	
		PROW/ADA:			N/A	Gutter Ponding?	N/A		Gutter Slope (%)	N/A	
	MI Y YAN	Not Found, R304.5.1, F	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Shut the start of the	11 13				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
and the first of the						X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
	1				N/A	X Walk 1 Width (in)	94.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	GIBBON RD					X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	