

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

7.8

1.4

Cross Street: ROSBERG\_LN Intersection ID: 44467 Main Street: BUCKHORN\_ST Location: SE **Overall Compliance: No** ADA ID: 749B75F2E36A Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 8.75

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

48.0 Yes

45.0 Yes

Ramp Length (in)

Ramp Width (in)

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)



Street 1 Name	ROSEBERG LN
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No

	A STATE OF	
	1000	
The state of the s		





	The second secon						' '			1 1 7	
The state of the s						N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
						N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
To the second						N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
The state of the s						N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
STEECH STEECH		Surveyor Notes:				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E COLUMN CONTRACTOR CO		N/A				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
						N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	-78 7 %					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
						N/A	Shared Landing?	N/A			
de A		PROW/ADA:				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	The state of the s	Not Found, R30	4.5.1			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	V X					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A							X Walk 1 Direction	To N		X Walk 2 Direction	N/A
						N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ROSEBERG LN						X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None						X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A					N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A						Road Slope (%)	N/A	N/A	Clear Space?	N/A
							Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
						N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:		\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
								N/A			N/A
									Yes	Surface Condition? (G/P)	Good
		7		TAMERA							