

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12428 Main Street: E\_7TH\_ST Cross Street: N\_CALDWELL\_ST Location: W

ADA ID: 74DDA343958E Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 47.5

Codes/Mitigation Info/Possible Solution Field Measurements/Con

	Codes/Mitigation Info/F				
0,	S. Fills				
3	E.	ė.	No.		
			1		

Street 1 Name

N CALDWELL ST

Stop Condition-Street 2

Signal

Street 2 Name

E 7TH ST

Stop Condition-Street 1

Signal

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Total Cost:

R304.5.1, R304.2.2







3200.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	69.0	No	Ramp Slope (%)	10.7			
No	No Ramp Width (in)		Yes	Ramp XSlope (%)	1.7			
N/A	N/A Flare Type LT		N/A	N/A Flare Type RT				
N/A	N/A Flare Slope LT (%)		N/A	N/A Flare Slope RT (%)				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	2.0	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes			
	X Walk 1 Direction	To SE		X Walk 2 Direction	To NE			
N/A	X Walk 1 Width (in)	105.0	N/A	X Walk 2 Width (in)	85.0			
	X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	1.3			
	X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	0.3			
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes			
	Road Slope (%)	0.8	N/A	Clear Space?	N/A			
	Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			

Yes

Surface Condition? (G/P)

Good