

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28166	Main Street: FLAT_CREEK_DR		Cross	Cross Street: WAGON WHEEL_CT				Location:	NW
ADA ID: 75CC5C66B1F8	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	1.25	
С	Field Measurements/Component Compliance								
	Codes/Mitigation Info	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ram	n With	N/A	Ramp Length (in)	50.5		BlendTrans Slope (%)	Data 1.3
		Two New Directional Ramps o		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.3
		Equivalent.	•	N/A	Flare Type LT	-10.0 N/A		Flare Type RT	N/A
and the second		1		N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A N/A		N/A		DWS Provided?	N/A N/A
		Cumunum Natana			Landing Length (in)				
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
WHEEL		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
VIACOUL	122			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
the for the second	0	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and the second	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
and the second sec					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
A STATE OF THE STATE					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	WAGON WHEEL CT				X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.2		Clear Space?	N/A
					Road X Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		······ ·······························				N/A			N/A
						17/5	1		10/5





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

9.8