cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12897	Main Street: ABBEYDALE_DR			Street:	WOODGREEN_TR	Location:	NW		
ADA ID: 766E440BD769	Ramp Type: BlendTrans2 Ir			itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
20	NUMBER OF STREET	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
VOODCEREEN JIKA		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	62.0	Yes	BlendTrans Slope (%)	3.7
		Two New Directional Ramps or		Yes	Ramp Width (in)	67.0		BlendTrans XSlope (%)	5.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	• • • • •		N/A		N/A N/A
					Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
* 10 . A 10 . 10	1 Carlos Carlos			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
and and all					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	WOODGREEN TR				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	7.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	7.0		Clear Space?	N/A
					Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.1