## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46146 Main Street: ROCKY_FORD_CLUB_RD				ross Street: BEAVER_CREEK_DR				Location:	NW
ADA ID: 7679A8FD76F4	4 Ramp T	Ramp Type: BlendTrans1			ail: Fail Overall C	o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	72.0	Yes	BlendTrans Slope (%)	2.5
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	45.0	Yes	BlendTrans XSlope (%)	0.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		6		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
- T				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Leng		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
BEAVER OKIES				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second second				N/A	Shared Landing?	N/A			
Bartin Carlos		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A Marine Card		R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A PE MIL			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	THE I				X Walk 1 Direction	To S		X Walk 2 Direction	To E
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	BEAVER CREEK DR	_			X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	1.5
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	1.9
Street 2 Name	ROCKY FORD CLUB RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	0.5		Clear Space?	N/A
					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

0.3