

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---|-------------------------|---|------------------------|
| Intersection ID: 4419 | Main Street: DELROSE_LN | Cross Street: LARKHULL_DR | Location: SW |
| ADA ID: 76A6DF686865 | Ramp Type: BlendTrans1 | Initial Pass/Fail: Pass | Overall Compliance: No |
| Severity Score: 25.25 | | | |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | |



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.2.2-Perp, R304.3.2-Para, R305, R302.7.2

Total Cost: \$ 3950.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|--------|------------|-----------------------------|--------|
| N/A | Ramp Length (in) | 79.0 | Yes | BlendTrans Slope (%) | 1.9 |
| Yes | Ramp Width (in) | 135.0 | No | BlendTrans XSlope (%) | 3.3 |
| N/A | Flare Type LT | Sloped | N/A | Flare Type RT | Sloped |
| N/A | Flare Slope LT (%) | 11.7 | N/A | Flare Slope RT (%) | 4.5 |
| N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| Yes | Landing Length (in) | 54.0 | No | DWS Provided? | No |
| Yes | Landing Width (in) | 62.0 | N/A | DWS Contrast? | No |
| No | Landing Slope (%) | 6.1 | N/A | DWS Length (in) | N/A |
| Yes | Landing X Slope (%) | 1.0 | N/A | DWS Full Width? | No |
| N/A | Landing Curb? (Y/N) | No | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 1.5 |
| No | Gutter Lip Ht (in) | 1.0 | No | Gutter X Slope (%) | 3.9 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To E | | X Walk 2 Direction | N/A |
| | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 4.6 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 1.2 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 1.2 | | Clear Space? | Yes |
| | Road X Slope (%) | 4.6 | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | N/A | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | No | Curb Slope (%) | 14.6 |

Street 1 Name DELROSE LN
 Stop Condition-Street 1 StopSign
 Street 2 Name N/A
 Stop Condition-Street 2 N/A

