

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 2757	in Street: DAVIS LAKE DV	Cross Street		•	Location	C)M/
Intersection ID: 3757 Ma	Main Street: DAVIS_LAKE_PY		Cross Street: POPLAR_GROVE_DR		Location:	SW
ADA ID: 76F091BE5E68 Ra	тр Туре: Регр	Initial Pass/	ail: Fail Overall	Compliance	e: No Severity Score:	8.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance				
	Possible Solutions:	Compliance Description Data			Compliance Description Data	
	Remove & Replace Entire Ram). N/A	Ramp Length (in)	54.0 Ye	/es Ramp Slope (%)	5.7
		No	Ramp Width (in)	47.0 Ye	/es Ramp XSlope (%)	0.9
		N/A	Flare Type LT	N/A N	I/A Flare Type RT	N/A
DIVIE LANE IN LA 6		N/A	Flare Slope LT (%)	N/A N	I/A Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A N	I/A Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A N	V/A DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A N	I/A DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A N	I/A DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A N	I/A DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A N	V/A DWS Offset (in)	N/A
and the second second		N/A	Shared Landing?	N/A		
	PROW/ADA:	N/A	Gutter Ponding?	N/A N	V/A Gutter Slope (%)	N/A
	Not Found, R304.5.1	N/A	Gutter Lip Ht (in)	N/A N	V/A Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No N	V/A Painted X Walk2?	N/A
			X Walk 1 Direction	To N	X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A N	VA X Walk 2 Width (in)	N/A
Street 1 Name DAVIS LAK	E PY		X Walk 1 Slope (%)	7.3	X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Stop	Sign		X Walk 1 X Slope (%)	2.0	X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A	N/A	Ramp inside XWalk1?	N/A N	I/A Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A		Road Slope (%)	N/A N	I/A Clear Space?	N/A
			Road X Slope (%)	N/A N	I/A Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A N	I/A Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	1850.00	Obstruction Type		Storm Grate/Utility Type	
				N/A		N/A

