

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18263 Main Street: DRIFTER_DR **Cross Street: JALDENA_DR** Location: SE **Overall Compliance: No Severity Score:** ADA ID: 789C82C73E47 Ramp Type: Perp Initial Pass/Fail: Fail 25

Codes/Mitigation Info/Possible Solution



DRIFTER DR Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

· cccibic cciation	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
·	Ye
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.3	N/A
•	N/A
	N/A
	N/
	IN/A





Total Cost:



1850.00

Field Measurements/Component Compliance								
Compliance Description		Data	Comp	liance D	Description	Data		
N/A	Ramp Length (in)	47.0	Yes	Ramp S	Slope (%)	5.7		
Yes	Ramp Width (in)	48.0	No	Ramp X	(Slope (%)	7.9		
N/A	Flare Type LT	N/A	N/A	Flare Ty	/pe RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare S	lope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Tr	aversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS P	rovided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS C	ontrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS L	ength (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS F	ull Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS O	ffset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter 9	Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter 2	K Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted	X Walk2?	N/A		
	X Walk 1 Direction	To N		X Walk	2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk	2 Width (in)	N/A		
	X Walk 1 Slope (%)	4.8		X Walk	2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	3.1		X Walk	2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp ii	nside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear S	pace?	N/A		
	Road X Slope (%)	N/A	N/A	Clear S	pace to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm 0	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm 0	Grate/Utility Type			
		N/A				N/A		
			Yes	Surface	Condition? (G/P)	Good		