## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23799	Main Str	Main Street: LONGLEAF_DR			SPRUCE_PINE_PL	Location:	SE		
ADA ID: 798A9ADD8ECC	Ramp Ty	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A STATE AND A STATE OF	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	60.0	Yes	BlendTrans Slope (%)	3.4
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	5.5
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Row	23 . 4			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Contraction of the second seco	E			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A CARACTER	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E F				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	2 Martin Contraction	•		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
5	and the second			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	and it	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	- 14 a 16 74 19				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	LONGLEAF DR	-			X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	8.1
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	9.6		X Walk 2 X Slope (%)	2.0
Street 2 Name	SPRUCE PINE PL			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	5.4		Clear Space?	N/A
					Road X Slope (%)	8.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

8.9