cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6128	Main St	Main Street: RUMSTONE_LN			Cross Street: STONE_MOUNTAIN_CT				NW
ADA ID: 79C54D165675	Ramp T	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ram	n With	N/A	Ramp Length (in)	95.0	Yes	BlendTrans Slope (%)	4.2
		Two New Directional Ramps of		No	Ramp Width (in)	43.0		BlendTrans XSlope (%)	4.5
		Equivalent.	-	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		NO LT SW		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		NO EI SW		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the	9		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
and the second se				N/A	Shared Landing?	N/A		Dwe enset (iii)	10/4
Elle		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
STOL	1 1 1 1 1 1			N/A	•		N/A	,	N/A
1 Sunt		Not Found, R304.5.1, R304.5.	.3	N/A	Gutter Lip Ht (in) Painted X Walk1?	1.0 No	N/A	Gutter X Slope (%) Painted X Walk2?	N/A N/A
				N/A			N/A		
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	STONE MOUNTAIN CT				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.4		Clear Space?	N/A
					Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.6