cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•			. ,					
Intersection ID: 26585	Main Str	Main Street: ARBORHILL_RD			Street:	MANOR_HOUSE_D	Location:	SW		
ADA ID: 7A670F3A2E23	Ramp Ty	Ramp Type: BlendTrans1			Pass/Fa	ail: Pass Overa	o Severity Score	: 0		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Curb Rai Two New Directional Ramps Equivalent.	Ram	p With	N/A	Ramp Length (in)	51.0	Yes	BlendTrans Slope (%)	4.1
			•	•	Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	0.7
			•		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
					N/A	Flare Slope LT (%)	3.3		Flare Slope RT (%)	3.0
					N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
ARBON					No	Landing Length (in)	44.0	Yes	DWS Provided?	Yes
		Surveyor Notes:			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
5		N/A			No	Landing Slope (%)	2.6	Yes	DWS Length (in)	24.0
					Yes	Landing X Slope (%)	0.2	Yes	DWS Full Width?	Yes
					N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.0
BI BI					N/A	Shared Landing?	No			
The ball		PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.0
		Not Found, R304.2.1, R304.2.2-Per		-Perp.	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.8
	in the second	R304.3.2-Para, R305.2			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
	A S					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	MANOR HOUSE DR	-				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	0.4		Clear Space?	Yes
						Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.9