

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15858 Main Street: E_W_T_HARRIS_BV				Cross	Stroot	SNOW I N			Location:	NE
				Cross Street: SNOW_LN						
ADA ID: 7B6CAE330AC6 Ramp		Type: Directional1		Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	26.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
小学の学校		Possible Solutions:		Compliance Description D			Data	ata Compliance Description		Data
BARAWAY DE	L NEW CONTRACTOR	Remove & Replace Entire I	Ramp.		N/A	Ramp Length (in)	29.0	N/A	Grade Break?	N/A
			-		Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0
de la					No	Ramp Slope (%)	15.9	N/A	Grade Break XSlope (%)	0.0
E. E.	6. A				No	Ramp XSlope (%)	2.3			
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
E M I HARA		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E STATE	the second LAN	N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
E to S	Shloone				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	and and and the				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	G man Man				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
ALC: No.	NAME -	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	NAL CONSIGNATION	R304.2.2, R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
A CONTRACTOR	I BALL STREAM	·			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
					N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	a second second				N/A	Painted X Walk1?	No		Road Slope (%)	1.6
Street 1 Name	SNOW LN					X Walk 1 Direction	To S		Road X Slope (%)	2.1
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	2.1	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$ 1	600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	N/A	Curb Slope (%)	12.1

