

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: E_MARTIN_LUTHER_KING_JR_CBVss Street: S_COLLEGE_ST Location:

ADA ID: 7BE6AF39E3BD Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



E MARTIN LUTHER KING JR BV Street 1 Name Stop Condition-Street 2 Signal Street 2 Name S COLLEGE ST Stop Condition-Street 1 Signal Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes: N/A

PROW/ADA:

Not Found, R304.5.1 R304.5.3

		N/A
		N/A
1, R304.2.2	2,	N/A
•	•	N/A
		N/A
		N/A
\$	3200.00	N/A

Total Cost:	\$ 3200.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	oliance Description	Data		
N/A	Ramp Length (in)	72.0	No	Ramp Slope (%)	9.4		
No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	5.1		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes		
	X Walk 1 Direction	To SW		X Walk 2 Direction	To SE		
N/A	X Walk 1 Width (in)	101.0	N/A	X Walk 2 Width (in)	114.0		
	X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	5.4		
	X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	3.3		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes		
	Road Slope (%)	3.2	N/A	Clear Space?	N/A		
	Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		





