


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 9177	Main Street: MARIETTA_ST	Cross Street: KALYNNE_ST	Location:	S
ADA ID: 7CB626004C9D	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 35

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance									
	Possible Solutions:		<b>Compliance</b>			<b>Description</b>			<b>Data</b>			
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>N/A</b>	Ramp Length (in)		<b>55.0</b>		<b>No</b>	Ramp Slope (%)		<b>17.1</b>	
			<b>No</b>	Ramp Width (in)		<b>46.0</b>		<b>No</b>	Ramp XSlope (%)		<b>2.4</b>	
			<b>N/A</b>	Flare Type LT		<b>N/A</b>		<b>N/A</b>	Flare Type RT		<b>N/A</b>	
			<b>N/A</b>	Flare Slope LT (%)		<b>N/A</b>		<b>N/A</b>	Flare Slope RT (%)		<b>N/A</b>	
			<b>N/A</b>	Flare Traversable LT?		<b>N/A</b>		<b>N/A</b>	Flare Traversable RT?		<b>N/A</b>	
			<b>N/A</b>	Landing Length (in)		<b>N/A</b>		<b>N/A</b>	DWS Provided?		<b>N/A</b>	
			<b>N/A</b>	Landing Width (in)		<b>N/A</b>		<b>N/A</b>	DWS Contrast?		<b>N/A</b>	
			<b>N/A</b>	Landing Slope (%)		<b>N/A</b>		<b>N/A</b>	DWS Length (in)		<b>N/A</b>	
			<b>N/A</b>	Landing X Slope (%)		<b>N/A</b>		<b>N/A</b>	DWS Full Width?		<b>N/A</b>	
Surveyor Notes:		<b>N/A</b>			<b>N/A</b>			DWS Offset (in)			<b>N/A</b>	
PROW/ADA:		<b>Not Found, R304.5.1, R304.2.2, R304.5.3</b>			<b>N/A</b>							
					<b>N/A</b>			Gutter Ponding?			<b>Yes</b>	
					<b>N/A</b>			Gutter Lip Ht (in)			<b>N/A</b>	
					<b>N/A</b>			Painted X Walk1?			<b>No</b>	
					<b>To N</b>			X Walk 2 Direction			<b>N/A</b>	
					<b>N/A</b>			X Walk 2 Width (in)			<b>N/A</b>	
					<b>4.3</b>			X Walk 2 Slope (%)			<b>N/A</b>	
					<b>4.1</b>			X Walk 2 X Slope (%)			<b>N/A</b>	
					<b>N/A</b>			Ramp inside XWalk2?			<b>N/A</b>	
					<b>4.1</b>			Clear Space?			<b>N/A</b>	
					<b>4.3</b>			Clear Space to XWalk (in)			<b>N/A</b>	
					<b>N/A</b>			Storm Grate/Utility Hazard?			<b>N/A</b>	
								Storm Grate/Utility Type				
					<b>N/A</b>						<b>N/A</b>	
								Surface Condition? (G/P)			<b>Good</b>	
Total Cost:		\$ 1850.00										

