

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4516	Main Str	Main Street: ASTORIA_DR			Cross Street: DASHIEL_DR					NE
ADA ID: 7EECF88E05FB	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			Data
3-1-1		Remove & Replace	Entire Ramp	N/A	Ramp Len	ngth (in)	60.0	Yes	Ramp Slope (%)	5.0
				No	Ramp Wic		45.0	No	Ramp XSlope (%)	2.1
		n an		N/A	•		N/A	N/A	Flare Type RT	N/A
		ii a		N/A	Flare Slop	be LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A		versable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing L	ength (in)	N/A	N/A	DWS Provided?	N/A
DASHIEL DR 5		Surveyor Notes:		N/A	-		N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing S	lope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	-	Slope (%)	N/A	N/A	DWS Full Width?	N/A
- China - Co				N/A	-	urb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	0	()	N/A			
		PROW/ADA:		N/A		0	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.	1 R304 5 3	N/A		8	N/A		Gutter X Slope (%)	N/A
			1, 1004.0.0	N/A	- 1	. ,	No	N/A	Painted X Walk2?	N/A
					X Walk 1 [Direction	To W		X Walk 2 Direction	N/A
				N/A	X Walk 1 \	Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ASTORIA DR				X Walk 1 S	()	4.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A		de XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slop		N/A	N/A	Clear Space?	N/A
					Road X SI	. ,	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/#		,	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00	Obstructio				Storm Grate/Utility Type	
		-				21	N/A			N/A
4										

Yes Surface Condition? (G/P)

Good

