cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2407	rsection ID: 2407 Main Street: ACACIA_RIDGE_CT Cross Street: HIDDEN_MEADOW_LN							Location:	W
ADA ID: 7F74E34B069B		Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				
		tial Pass/Fail: Fail Overall Compliance: No Severity Score: 25 Field Measurements/Component Compliance							
		fo/Possible Solution Possible Solutions:					Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	<u>Data</u> 5.8
and the second		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	12.0
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A CAR				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1 strain			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
CT CT CT CT	3/11 -			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
PROW/ADA: Not Found, R304.5.3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HIDDEN MEADOW LN				X Walk 1 Slope (%)	6.8		X Walk 2 Slope (%)	1.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	4.6
Street 2 Name	ACACIA RIDGE CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.8	N/A	Clear Space?	N/A
					Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

5