

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10026800 Main Street: FOREST POINT BV Cross Street: N/A Location: SW **Overall Compliance: No** ADA ID: 805101962FF1 Ramp Type: Directional1 Initial Pass/Fail: Pass **Severity Score:** 15

Codes/Mitigation Info/Possible Solution



ENTRANCE Street 1 Name Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A

Pro-	1 Ossible Solutions.
の大きながら	Remove & Replace Entire Ramp. Remove & Replace Gutter.
1 March 100	Surveyor Notes: N/A
	PROW/ADA: Not Found, R304.2.2-Perp, R304.3.2- Para, R305, R304.5.4
7	

			N/A	
			N/A	
Notes:			N/A	
			Yes	
			Yes	
			No	
			Yes	
DA:			N/A	
ound, R304.2.2-Per	N/A			
R305, R304.5.4	• •		Yes	
			Yes	
			N/A	
			N/A	
			Yes	
t·	\$	2350.00		

Total Cost:	\$	2350.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	46.0	Yes	Grade	Break?	Yes	
Yes	Ramp Width (in)	50.0	Yes	Grade	Break Slope (%)	4.0	
Yes	Ramp Slope (%)	6.1	Yes	Grade	Break XSlope (%)	2.4	
Yes	Ramp XSlope (%)	1.7					
N/A	Flare Type LT	N/A	N/A	Flare ⁻	Гуре RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare ⁻	Traversable RT?	N/A	
Yes	Landing Length (in)	48.0	No	DWS	Provided?	No	
Yes	Landing Width (in)	50.0	N/A	DWS	Contrast?	No	
No	Landing Slope (%)	4.1	N/A	DWS	Length (in)	N/A	
Yes	Landing X Slope (%)	2.8	N/A	DWS	Full Width?	No	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A	
N/A	Shared Landing?	No	N/A	DWS	Offset RT (in)	N/A	
Yes	Gutter Ponding?	No	No	Gutter	Slope (%)	8.7	
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter	X Slope (%)	1.7	
N/A	Painted X Walk1?	No		Road	Slope (%)	2.3	
	X Walk 1 Direction	To N		Road 2	X Slope (%)	7.1	
	X Walk 1 Width (in)	N/A		Clear	Space?	Yes	
	X Walk 1 Slope (%)	2.3	N/A	Clear	Space to XWalk (in)	N/A	
	X Walk 1 X Slope (%)	7.1	Yes	Storm	Grate/Utility Hazard?	No	
N/A	Ramp inside XWalk1?	N/A		Storm	Grate/Utility Type		
Yes	Any Obstructions?	No				N/A	
	Obstruction Type		Yes	Surfac	e Condition? (G/P)	Good	
		N/A	No	Curb S	Slope (%)	12.3	





