## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpretion ID: 17202										NW
Intersection ID: 17202	Main Street: TYNER_ST			Cross	s Street:	WOODLAWN_RD	Location:	IN VV		
ADA ID: 813FA985F475	Ramp Type: BlendTrans1			Initial	Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	5
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
C AAM AND C		Remove & Replace Cu	rb Ram	p With	N/A	Ramp Length (in)	104.0	Yes	BlendTrans Slope (%)	5.0
		Two New Directional R	nal Ramps or	•	Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	1.2
		Equivalent. Remove & Replace Gutter.	Replac	eplace	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
					N/A	Flare Slope LT (%)	2.2	Yes	Flare Slope RT (%)	7.7
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes	
					Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
				Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes	
		N/A			Yes	Landing Slope (%)	0.8	Yes	DWS Length (in)	24.0
					Yes	Landing X Slope (%)	1.9	Yes	DWS Full Width?	Yes
	110				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.5
p day				N/A	Shared Landing?	No				
		PROW/ADA:			Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.1
		Not Found, R305.2, R30	04.5.4		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.0
					N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
A Province of the second					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
						X Walk 1 Width (in)	108.0		X Walk 2 Width (in)	N/A
Street 1 Name	I-77 EXIT	_				X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	4.9		Clear Space?	Yes
						Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	3950.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

8.0