cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11693 Mai	693 Main Street: E_12TH_ST		Cross Street: N_COLLEGE_ST				Location: E		
ADA ID: 81D6D990D7F1 Rar	Ramp Type: BlendTrans1		Initial Pass/Fail: Fail Overall Compliand			ice: No	Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	<u>c</u>	Compliance Description Data				Compliance Description		
	Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	Nith N	I/A	Ramp Length (in)	49.0	Yes	BlendTrans Slope (%)	2.1	
			lo	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	5.2	
		N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		Ν	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		Ν	I/A	Shared Landing?	N/A				
	PROW/ADA:	Ν	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	N	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		Ν	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes	
	and the second se			X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	87.0	
Street 1 Name N COLLEGI	E ST			X Walk 1 Slope (%)	8.4		X Walk 2 Slope (%)	0.4	
Stop Condition-Street 1 Si	gnal			X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	6.9	
Street 2 Name E 12TI	I ST	Ν	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes	
Stop Condition-Street 2 Si	gnal			Road Slope (%)	1.0		Clear Space?	N/A	
	-			Road X Slope (%)	5.8	N/A	Clear Space to XWalk (in)	N/A	
		Ν	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

17.1