## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

13.1

Intersection ID: 18798	Main Street: PRENTICE_PL			s Street:	SENECA_PL	Location:	SW		
ADA ID: 8210996AFEF0	Ramp Type: ParaDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Johnstein	Possible Solutions:					ata Compliance Description		Data
		Remove & Replace Curb Ra	mn With	N/A	Ramp Length LT (in)	40.0		Ramp Length RT (in)	63.0
		Two New Directional Ramps	•	Yes	Ramp Width LT (in)	67.0	Yes	Ramp Width RT (in)	56.0
		Equivalent.		No	Ramp Slope LT (%)	8.9	No	Ramp Slope RT (%)	8.9
				Yes	Ramp XSlope LT (%)	1.6	No	Ramp XSlope RT (%)	2.1
		Surveyor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
SENEGA PL				N/A	Landing Width (in)	N/A		DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		ζ, γ	
S				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The second secon	PLAN	PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
E/		R304.3.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
	the lot we want			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	3.5
Street 1 Name	PRENTICE PL	-			X Walk 1 X Slope (%)	7.2		X Walk 2 X Slope (%)	3.5
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	SENECA PL				Road Slope (%)	7.2	N/A	Clear Space?	N/A
Stop Condition-Street 2	None				Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	3200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

