

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54402Main Street:SPRINGMAN_LNCross Street:LOMA_LINDA_LNLocation:SEADA ID: 82229F95C356Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 2

Street 2 Name

N/A

Stop Condition-Street 1

N/A

TO CONTROL CON	
Possible Solutions:	
Remove & Replace Entire Ramp.	ı
	`
	ı
	I
	I
	I
Surveyor Notes:	ı
N/A	ı
	!
DDOW/ADA	
PROW/ADA:	
Not Found, R304.5.3	
	'
	ı
	'

Total Cost:



1850.00

Field Measurements/Component Compnance						
Compl	iance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	6.2	
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	8.3	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	6.2		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	

