cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 21551 Main Street: CHAMPAIGN_ST Cross Street: MARKWORTH_AV							l continu.	05
	Main Street: CHAMPAIGN_ST				Location:	SE		
ADA ID: 8225CF5AEC55 Ramp Type: PerpDiag		Initial Pase	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	37.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
B 5 MARKADORATI AN B 5 MARKADORATI AN B 5 MARKADORATI AN	Possible Solutions:	<u>Cc</u>	Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp W	ith N/.	A Ran	mp Length (in)	44.0	No	Ramp Slope (%)	8.4
	Two New Directional Ramps or Equivalent.	Ye	s Ran	mp Width (in)	48.0	No	Ramp XSlope (%)	8.1
		N/2	A Flai	re Type LT	N/A	N/A	Flare Type RT	N/A
		N/.	A Flai	re Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N /.	A Flar	re Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/.	A Lan	nding Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/.	A Lan	nding Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/.	A Lan	nding Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/.	A Lan	nding X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N /.	A Lan	nding Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	100	N/.	A Sha	ared Landing?	N/A			
	PROW/ADA:	N/.	A Gut	tter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
" Then I when	Not Found, R304.2.2, R304.5.3	N//	A Gut	tter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/.	A Pair	nted X Walk1?	No	N/A	Painted X Walk2?	No
- Carlo - Carl			ХW	Valk 1 Direction	To N		X Walk 2 Direction	To W
		N/.	A XW	Valk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name MARKWORTH	AV		ХW	Valk 1 Slope (%)	4.6		X Walk 2 Slope (%)	7.4
Stop Condition-Street 2 StopS	gn		ХW	Valk 1 X Slope (%)	8.9		X Walk 2 X Slope (%)	2.1
Street 2 Name CHAMPAIGN	ST	N/.	A Ran	mp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	ne		Roa	ad Slope (%)	7.1	N/A	Clear Space?	N/A
			Roa	ad X Slope (%)	6.6	N/A	Clear Space to XWalk (in)	N/A
		N/.	A Any	Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	00.00	Obs	struction Type			Storm Grate/Utility Type	
					N/A			N/A

