## cole

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: 18684	Main Street: LAMONT_DR		Cross Street: MURRAYHILL_RD				Location:	Ν	
ADA ID: 839BB11AB8C0	Ramp Ty	Ramp Type: ParaDiag		itial Pass/Fail: Pass Overall Compliance: N			Severity Score:	5.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
1 8-312 13-1 - 32 1	12. 41 B	Possible Solutions:	Com	Compliance Description Data Comp			pliance Description Data		
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.	th N/A	Ramp Length LT (in)	48.0	N/A	Ramp Length RT (in)	74.0	
			Yes	Ramp Width LT (in)	71.0	Yes	Ramp Width RT (in)	50.0	
			Yes	Ramp Slope LT (%)	7.9	Yes	Ramp Slope RT (%)	7.1	
			No	Ramp XSlope LT (%)	3.7	Yes	Ramp XSlope RT (%)	1.0	
			Yes	Landing Length (in)	72.0	Yes	DWS Provided?	Yes	
			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
A DE AN A DE A	A	Surveyor Notes:	No	Landing Slope (%)	3.7	Yes	DWS Length (in)	24.0	
	9ª	N/A	No	Landing X Slope (%)	4.9	Yes	DWS Full Width?	Yes	
E Contractions		PROW/ADA: R304.5.3, R304.2.2-Perp, R304.3.2- Para, R304.5.4	N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0	
			N/A	Shared Landing?	No				
			Yes	Gutter Ponding?	No	No	Gutter Slope (%)	15.5	
			Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	5.6	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	9.0		X Walk 2 Slope (%)	3.6	
Street 1 Name	MURRAYHILL RD			X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	7.8	
Stop Condition-Street 1	StopSign		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Street 2 Name	LAMONT DR			Road Slope (%)	6.1	N/A	Clear Space?	Yes	
Stop Condition-Street 2	None			Road X Slope (%)	9.1	N/A	Clear Space to XWalk (in)	N/A	
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
				Obstruction Type			Storm Grate/Utility Type		
		Total Cost: \$ 3950	0.00		N/A			N/A	
						Yes	Surface Condition? (G/P)	Good	
						N/A	Curb Slope (%)	17.7	

