

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.1

0.7

N/A

Good

Surface Condition? (G/P)

N/A

Intersection ID: 10541 Main Street: CANTON PL **Cross Street: POLK\_ST** Location: Ε ADA ID: 83B022F1C90A Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

> Codes/Mitigation Info/Possible Solution mpliance

	Codes/Mitigation Info/P
And the second	
	S.
ė . ė	<b>ENTION PA</b>
	The state of the s

Street 1 Name	POLK ST
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

fo/Possible Solution		Field Measurements/Component Compliance				
Possible Solutions:	Comp	liance Description	Data	Comp	liance Description	
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	62.0	Yes	Ramp Slope (%)	
	No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	
Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	
N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	
7	N/A	Shared Landing?	N/A			
PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	
Not Found, R304.5.1	N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	
		X Walk 1 Direction	To NW		X Walk 2 Direction	
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	
		X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	
		X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	
		Road Slope (%)	N/A	N/A	Clear Space?	
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	
Total Cost: \$ 185	50.00	Obstruction Type			Storm Grate/Utility Type	





