

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15211	Main Street, EAST DV							Location:	Е
	Main Street: EAST_BV		01055	Cross Street: SCOTT_AV					<u> </u>
ADA ID: 84493ED0E281	Ramp Type: BlendTrans2		Initial	Initial Pass/Fail: Fail Overall Complia			ice: No	Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible	Possible Solutions:		Compliance Description		Data	Comp	ance Description	Data
	Rem	nove & Replace Curb Ram	p With	N/A	Ramp Length (in)	66.0	Yes	BlendTrans Slope (%)	3.6
		New Directional Ramps o	•	Yes	Ramp Width (in)	130.0	No	BlendTrans XSlope (%)	7.7
	Equi	ivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Car I			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	AN I			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 yes			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyo	/or Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	a star			N/A	Shared Landing?	N/A			
	PROW/	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not I	Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	C Mrs				X Walk 1 Width (in)	114.0		X Walk 2 Width (in)	108.0
Street 1 Name SC	OTT AV				X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	0.8
Stop Condition-Street 1	Signal				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	2.9
Street 2 Name E	AST BV			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 2	Signal				Road Slope (%)	4.3		Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Co	Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.6