cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27340	Main Str	Main Street: SHINING_ROCK_CT		Cross Street: STONEPATH_LN				Location:	N	
ADA ID: 85E0754AD6E1	Ramp Ty	Ramp Type: BlendTrans2			ail: Pass Overall	o Severity Score:	0			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	E HILLE LE	Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	44.0	Yes	BlendTrans Slope (%)	2.6	
		Two New Directional Ramps of	•	Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	1.9	
		Equivalent. Remove & Replace Gutter.	e	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped	
				No	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No	
				N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes	
		N/A		N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.5	
				N/A	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes	
				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	4.0	
C. TAMA				N/A	Shared Landing?	No				
A AND AND		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.4	
		Not Found, R304.2.3, R305.2,		Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.7	
		R304.5.3	0.2,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
All and and and and					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	STONEPATH LN	-			X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	5.6	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	6.0		X Walk 2 X Slope (%)	2.4	
Street 2 Name	SHINING ROCK CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	StopSign				Road Slope (%)	2.8		Clear Space?	Yes	
					Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A	
				Yes	Any Obstructions?	No		Storm Grate/Utility Hazard?	No	
		Total Cost: \$	3950.00		Obstruction Type			Storm Grate/Utility Type		
		······ • • • • • • • • • • • • • • • •				N/A			N/A	
						17/4			100	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.9