


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|   |                                |   |                        |
|---|--------------------------------|---|------------------------|
| Intersection ID: 10025796               | Main Street: EDGEHILL_RD_NORTH | Cross Street: N/A                       | Location: SE           |
| ADA ID: 87DA79D090F8                    | Ramp Type: PerpDiag            | Initial Pass/Fail: Fail                 | Overall Compliance: No |
| Codes/Mitigation Info/Possible Solution |                                | Field Measurements/Component Compliance |                        |
| Severity Score: 22.5                    |                                |   |                        |

|   |  |            |                       |       |            |                             |       |
|---|--|------------|-----------------------|-------|------------|-----------------------------|-------|
|         | Possible Solutions:  | Compliance | Description           | Data  | Compliance | Description                 | Data  |
|   | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | N/A        | Ramp Length (in)      | 63.0  | No         | Ramp Slope (%)              | 10.8  |
|   |  | No         | Ramp Width (in)       | 37.0  | Yes        | Ramp XSlope (%)             | 4.5   |
|   |  | N/A        | Flare Type LT         | N/A   | N/A        | Flare Type RT               | N/A   |
|   |  | N/A        | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A   |
|   |  | N/A        | Flare Traversable LT? | N/A   | N/A        | Flare Traversable RT?       | N/A   |
|   |  | N/A        | Landing Length (in)   | N/A   | N/A        | DWS Provided?               | N/A   |
|   |  | N/A        | Landing Width (in)    | N/A   | N/A        | DWS Contrast?               | N/A   |
|   |  | N/A        | Landing Slope (%)     | N/A   | N/A        | DWS Length (in)             | N/A   |
|   |  | N/A        | Landing X Slope (%)   | N/A   | N/A        | DWS Full Width?             | N/A   |
|   |  | N/A        | Landing Curb? (Y/N)   | N/A   | N/A        | DWS Offset (in)             | N/A   |
|   |  | N/A        | Shared Landing?       | N/A   |            |                             |       |
|   |  | N/A        | Gutter Ponding?       | N/A   | N/A        | Gutter Slope (%)            | N/A   |
|   |  | N/A        | Gutter Lip Ht (in)    | N/A   | N/A        | Gutter X Slope (%)          | N/A   |
|   |  | N/A        | Painted X Walk1?      | No    | N/A        | Painted X Walk2?            | No    |
|   |  |            | X Walk 1 Direction    | To SW |            | X Walk 2 Direction          | To SE |
|   |  | N/A        | X Walk 1 Width (in)   | N/A   | N/A        | X Walk 2 Width (in)         | N/A   |
|   |  |            | X Walk 1 Slope (%)    | 3.3   |            | X Walk 2 Slope (%)          | 10.2  |
|   |  |            | X Walk 1 X Slope (%)  | 3.4   |            | X Walk 2 X Slope (%)        | 0.9   |
|   |  | N/A        | Ramp inside XWalk1?   | N/A   | N/A        | Ramp inside XWalk2?         | N/A   |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2</p> |  |            | Road Slope (%)        | 4.5   | N/A        | Clear Space?                | N/A   |
|   |  |            | Road X Slope (%)      | 0.0   | N/A        | Clear Space to XWalk (in)   | N/A   |
| Total Cost:   |  | N/A        | Any Obstructions?     | N/A   | N/A        | Storm Grate/Utility Hazard? | N/A   |
|   |  |            | Obstruction Type      |       |            | Storm Grate/Utility Type    |       |
|   |  |            |                       | N/A   |            |                             | N/A   |
|   |  |            |                       |       | Yes        | Surface Condition? (G/P)    | Good  |

