## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11295	section ID: 11295 Main Street: AVENTIDE_LN		Cross	Cross Street: CHANTRESS_LN				Location:	NE
ADA ID: 880DD4980165	: 880DD4980165 Ramp Type: BlendTrans1		Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	0	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ram	np With	N/A	Ramp Length (in)	47.0	Yes	BlendTrans Slope (%)	4.0
		Two New Directional Ramps	or	No	Ramp Width (in)	39.0	Yes	BlendTrans XSlope (%)	1.7
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Se al			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	C. I	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		CURB LIP 0.5		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	BS LN			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		-		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	and the second			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	-	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		····, ····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name CH	ATRESS LN				X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.7		Clear Space?	N/A
					Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.3