cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9973	Main Street: CAMPUS_ST				Street:	FRENCH_ST	Location:	SW		
ADA ID: 88E2C975F652 Ramp Type: BlendTrans1			initial	Pass/Fa			33.75			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description Data Compli			liance Description	Data	
		Remove & Replace Cu Two New Directional R	-	N/A	Ramp Length (in)	65.5	Yes	BlendTrans Slope (%)	3.3	
				No	Ramp Width (in)	42.0	No	BlendTrans XSlope (%)	7.9	
		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
J					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A AND AND AND AND AND AND AND AND AND AN					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
FRENCH &					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Children and and and and				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	San Ar Sher	A contract of the second se			N/A	Shared Landing?	N/A			
No.	A STATE OF THE STA	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1,	R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
						X Walk 1 Direction	To E		X Walk 2 Direction	To N
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	CAMPUS ST					X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	0.1
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	8.2
Street 2 Name	FRENCH ST				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	3.0		Clear Space?	N/A
						Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

23.8