

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8515Main Street: ATANDO_AVCross Street: STATESVILLE_AVLocation: SWADA ID: 89AC4F6BBB39Ramp Type: PerpInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 31.25

Codes/Mitigation Info/Possible Solution



Street 1 Name
Statesville AV
Stop Condition-Street 2
Signal
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Pomovo & Ponlaco Entiro Pama			
Remove & Replace Entire Ramp.	N N		
	N		
	N		
	N		
	N		
Surveyor Notes:	N		
N/A	N		
	N		
	N		
	N		
PROW/ADA:	N		
Not Found, R304.5.1, R304.2.2	N		
Not 1 Julia, 1304.5.1, 1304.2.2	N		
	N		
	N		
	N		

	W. A		
##.		1	
	+		



Total Cost:



1850.00

Field Measurements/Component Compliance									
Comp	liance Description	Data	Compl	iance Description	Data				
N/A	Ramp Length (in)	138.0	No	Ramp Slope (%)	11.1				
No	Ramp Width (in)	34.0	Yes	Ramp XSlope (%)	3.5				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A				
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A				
	X Walk 1 Direction	То Е		X Walk 2 Direction	N/A				
N/A	X Walk 1 Width (in)	107.0	N/A	X Walk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A				
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A				
	Road Slope (%)	N/A	N/A	Clear Space?	N/A				
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
	Obstruction Type			Storm Grate/Utility Type					
		N/A			N/A				
			Yes	Surface Condition? (G/P)	Good				