## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



			-	-					
Intersection ID: 10741	Main Street: E_28TH_ST			street:	YADKIN_AV	Location:	W		
ADA ID: 89BB6C628FD0	Ramp Ty	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	42.0	Yes	BlendTrans Slope (%)	3.6
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	2.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Res 1				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		NO LT SW		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
· · · · · · · · · · · · · · · · · · ·				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	and the second second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Salar Salar	State States			N/A	Shared Landing?	N/A			
A A A A A		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the 1 the 1 states	ARE			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Dr Ant in the second	14 Mar 19				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
14 11 113	1. A. C. S.				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	YADKIN AV	-			X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	6.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	6.7		Clear Space?	N/A
					Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.9