

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

18.9

Intersection ID: 10020582	10020582 Main Street: BASCOM_ST				N/A	Location:	N		
ADA ID: 8A41CFD68D15	Ramp Type: Para			Initial Pass/Fail: Fail Overall Compliance: N					12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:								bliance Description	Data
Topa and read	Griefe	Remove & Replace Entire Ran	n n	<u>00111</u>	Ramp Length LT (in)	100.0		Ramp Length RT (in)	115.0
The state 200		Remove & Replace Entire Ran	np.	Yes	Ramp Width LT (in)	112.0		Ramp Width RT (in)	116.0
10 - 10 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1				No	Ramp Slope LT (%)	9.3		Ramp Slope RT (%)	0.2
A state of the second s				Yes	Ramp XSlope LT (%)	1.2		Ramp XSlope RT (%)	1.2
				N/A	Landing Length (in)		N/A	DWS Provided?	N/A
				N/A	Landing Width (in)		N/A	DWS Contrast?	N/A
	190	Surveyor Notes:		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
The set of	13.5	RT RP < 5%		N/A	Landing X Slope (%)		N/A	DWS Full Width?	N/A
	< Y WEAV V	RT RP < 5%		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second s				N/A	Shared Landing?	N/A		DWS Onset (III)	11/2
CRA SE SI				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The first the second	A W	PROW/ADA:		N/A	Gutter Lip Ht (in)		N/A	Gutter X Slope (%)	N/A
	Carlos .			N/A N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
1 plant	A CALL	R304.3.2		N/A			N/A		
				N 1/A	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
1 98 112 15	Also Maria			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		1			X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A
Street 1 Name	BASCOM ST				X Walk 1 X Slope (%)	5.5		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A				Road Slope (%)	N/A		Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	1600.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

