

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · ·										
Intersection ID: 14314	Main Street: TREMONT_ST			Cross Street: SOUTH_BV					NE	
ADA ID: 8B8758BC3000	Ramp Ty	Ramp Type: Perp			ail: Fail Overall	o Severity Score:	13.75			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Data			Compliance Description		Data	
	Rall N.	Remove & Replace Entire Ramp	-	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	9.0	
A A A A A A A A A A A A A A A A A A A				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.1	
	Sec. S			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
CONTRACTOR AND	A A Secille			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
A A A A A A A A A A A A A A A A A A A				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	1 7 7 8			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	base 1 mar	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
IREMON-				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
Anna Barris	1010			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	a the s	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	CO.LA	1004.2.2		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	119.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	E TREMONT AV	-			X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	7.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
		·			51	N/A			N/A	
							1			

Yes Surface Condition? (G/P)

Good