

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52118	Main Sti	Main Street: REAMES_RD			Cross Street: LONGVIEW_CLUB_LN				Location: S		
ADA ID: 8C119876B49A	Ramp T	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Com			pliance: No Severity Score: 21.2		21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
A POINT AND A POIN	31 CALORIA	Possible Solutions:			Comp	iance Description Data Complia			liance Description	Data	
A A A	Land And	Remove & Repla	ce Entire Ramp.		N/A	Ramp Length (in)	72.5	Yes	Ramp Slope (%)	6.2	
A Strike		4	•		No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	6.4	
a she will be	AN A				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	AND A	à			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		ă la constante de la constante			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
C & C OT	A Barren al				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	the starting of the party of the	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	THE SECTION A	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
A CAR BALLER		ŧ.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	EP LUCE A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
a an Frankler	2 1 2 2 2 2 2	Not Found, R30	4.5.1. R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
an Million Million		,	,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
We A COMPANY						X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
	1 4 C				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	LONGVIEW CLUB LN	_				X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	10.9		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$ 13	850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

es Surface Condition? (G/P)

Good

