

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12279	Main Street: S_MINT_ST			eet:	W_MARTIN_LUTHER	Location:	S			
ADA ID: 8D2F30F43DE0	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Complia			ance: No Severity Score:		8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	1 4 7 7 7	Possible Solutions:	Compliance Description Data Co				Comp	ompliance Description Data		
An and a second	(A)	Remove & Replace Entire Ramp	. N	I/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.2	
	71 73	······		lo	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	0.7	
	1/14		N	/ <b>A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the states of th	A George		N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	ATTE .		N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the structure of the second se	1/19		N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
S S AND	SU.	Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
Strain Contraction	1000	N/A	N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
E. Yr			N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	C G		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N	I/A	Shared Landing?	N/A				
A JAK STAN	" A de	PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
1 Caller Andrew		Not Found, R304.5.1	N	/ <b>A</b>	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N	I/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
All AND					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
the second second second	· * 2		N	I/A	X Walk 1 Width (in)	95.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name W MARTIN LUTHER KING JR BV					X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A		N	I/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			Ν	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
					••	N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

